

0008Z 11 OCT 1963

S E C R E T

DIRECTOR

25X1A

OPS 1 - 7

ROUTINE

TOR: 1002Z 11 OCT 1963

IN 95205

25X1A

25X1A

212

A. 5231

B. 559

C. 11 OCT 63 FOR 7 PLUS 00

D. HQS DIRECTED MSN WITH

E. (1) FUEL PRESS IND FAILED IN FLIGHT. CORRECTIVE ACTION:

REPLACED FUEL PRESS TRANSMITTER.

F. NONE

G. NONE

END OF MESSAGE

S E C R E T